



HP® and CANON®

Monochrome Universal Chip Chart

It all starts with patented **universal** chips.
One chip. Multiple cartridges.

Visit us online for more information: www.scc-inc.com/ChipCenter/

NOTE: When searching for a particular OEM SKU or printer model on this document, press the "CTRL" key and "F" key on your keyboard at the same time in order to search.


June 22, 2015 2:05 PM
CH3499_UniversalMonoChipChart_V2







HP® and Canon® Monochrome Universal Chip Chart

NOTE: Chip appearance subject to change. Pictures and images may not be reflective of current offering.

| Static Control Chip | Printer Model | OEM SKU | Yield | Picture |
|--|---|------------------|-------|---|
| U16-2CHIP SSS™ 846 Chip Marking (U16-2) | HP® 700 M712, 700 M725 | CF214X (14X) | 17.5 |  |
| | HP® 5200 | Q7516A | 12k | |
| | Canon® LBP-3500, LBP-3900, LBP-3920, LBP-3950, LBP-3970, LBP-3980 | CRG-309, CRG-509 | | |
| | HP® M5025 MFP, M5035 MFP | Q7570A | 15k | |
| | Canon® LBP-8610, LBP-8620, LBP-8630 | CRG-527 | 17k | |
| | Canon® LBP-8710, LBP-8720, LBP-8730 | CRG-533H | | |




| Static Control Chip | Printer Model | OEM SKU | Yield | Picture |
|---|------------------------------------|------------------------------------|-------|--|
| U17-3CHIP SSS™ 1026 Chip Marking (U17-3) | HP® 1160, 1320, 3390 MFP, 3392 MFP | Q5949A | 2.5k |  |
| | Canon® LBP-3300, LBP-3360 | CRG-108, CRG-308, CRG-508, CRG-708 | | |
| | HP® 1300 | Q2613A | 2.5k | |
| | HP® P2014, P2015, M2727 MFP | Q7553A | 3k | |
| | Canon® LBP-3310, LBP-3370 | CRG-315, CRG-515, CRG-715 | | |
| | HP® 2300 | Q2610A | 6k | |
| | HP® 2410, 2420, 2430 | Q6511A | 6k | |
| | HP® P3005, M3027 MFP, M3035 MFP | Q7551A | 6.5k | |
| | HP® 4200 | Q1338A | 12k | |
| | HP® 4240, 4250, 4350 | Q5942A | 10k | |

| | | | | |
|---|-------------------------------------|---|-----|---|
| U18-3CHIP SSS™ 1026 Chip Marking (U18-3) | HP® 1320, 3390 MFP, 3392 MFP | Q5949X | 6k |  |
| | Canon® LBP-3300, LBP-3330, LBP-3360 | CRG-108II, CRG-308II, CRG-508II, CRG-708H | | |
| | HP® 1300 | Q2613X | 4k | |
| | HP® P2014, P2015, M2727 MFP | Q7553X | 7k | |
| | Canon® LBP-3310, LBP-3370 | CRG-315II, CRG-515II, CRG-715H | | |
| | HP® 2300 | Q2610A | 6k | |
| | HP® 2410, 2420, 2430 | Q6511X | 12k | |
| | HP® P3005, M3027 MFP, M3035 MFP | Q7551X | 13k | |
| | HP® 4200 | Q1338A | 12k | |
| | HP® 4250, 4350 | Q5942X | 20k | |
| | HP® 4300 | Q1339A | 18k | |
| | HP® 4345 MFP, M4345 MFP | Q5945A | 18k | |



HP® and Canon® Monochrome Universal Chip Chart

NOTE: Chip appearance subject to change. Pictures and images may not be reflective of current offering.



| Static Control Chip | Printer Model | OEM SKU | Yield | Picture |
|---|---|---|-------|---|
| U23CHIP SSS™ 1017 Chip Marking (U23) | Canon® D1120 MFP, D1150 MFP, D1170 MFP, D1180 MFP, D1320, D1350, D1370, MF6680 MFP, MF6780 MFP | CRG-120, CRG-320, CRG-720 | 5k |  |
| | HP® 500 M521/M525 MFP, P3011, P3015 | CE255A (55A) | 6k | |
| | Canon® LBP-3560, LBP-3580, LBP-6700, LBP-6780, LBP-6710i, LBP-6750 | CRG-324, CRG-524, CRG-724, GPR-40 | | |
| | HP® P1005, P1006 | CB435A (35A) (Intro) | 0.7k | |
| | Canon® LBP-3010, LBP-3018, LBP-3050, LBP-3100, LBP-3108, LBP-3150 | CRG-312 (Intro), CRG-712 (Intro), CRG-912 (Intro) | | |
| | HP® P1505, M1522 MFP, M1120 MFP | CB436A (36A) (Intro) | 1k | |
| Canon® LBP-3250 | CRG-313 (Intro), CRG-713 (Intro) | | | |
| U24CHIP SSS™ 1017 Chip Marking (U24) | HP® P1005, P1006 | CB435A (35A) | 1.5k |  |
| | Canon® LBP-3010, LBP-3050, LBP-3100, LBP-3150 | CRG-312, CRG-712, CRG-912 | | |
| | HP® P1505, M1120 MFP, M1522 MFP | CB436A (36A) | 2k | |
| | Canon® LBP-3250 | CRG-313, CRG-713 | | |
| | HP® P2035, P2055 | CE505A (05A) | 2.3k | |
| | Canon® 650i, LBP-3470, LBP-3480 | GPR-41 (Intro) | 2.1k | |
| | Canon® MF5840 MFP, MF5850 MFP, MF5870 MFP, MF5880 MFP, MF5940 MFP, MF5950 MFP, MF5960 MFP, MF5980 MFP, MF6140, MF6160 MFP, MF6180 MFP, LBP-6300, LBP-6650, LBP-6670, LBP-6680 | CRG-119, CRG-319, CRG-519, CRG-719 | | |
| HP® P4014, P4015, P4515 | CC364A (64A) | 10k | | |
| U25CHIP SSS™ 1017 Chip Marking (U25) | HP® 500 M521/M525 MFP, P3015 | CE255X (55X) | 12.5k |  |
| | Canon® LBP-3560, LBP-3580, LBP-6700, LBP-6780, LBP-6710i, LBP-6750 | CRG-324II, CRG-524II, CRG-724H, GPR-40H | | |
| | HP® P1007, P1008, P1106, P1108, M126 MFP, M1136 MFP, M1213 MFP, M1216 MFP, M1218 MFP | CC388A (88A) | 1.5k | |
| | Canon® LBP-3010, LBP-3050, LBP-3100, LBP-3150 | CRG-312, CRG-712, CRG-912 | | |
| | HP® P2055 | CE505X (05X) | 6.5k | |
| | Canon® 650i, LBP-3470, LBP-3480 | GPR-41 | 6.4k | |
| | Canon® MF5840 MFP, MF5850 MFP, MF5870 MFP, MF5880 MFP, MF5940 MFP, MF5950 MFP, MF5960 MFP, MF5980 MFP, LBP-6300, MF6140, MF6160 MFP, MF6180 MFP, LBP-6650, LBP-6670, LBP-6680 | CRG-119II, CRG-319II, CRG-519II, CRG-719H | | |
| | HP® P4015, P4515 | CC364X (64X) | 24k | |





HP® and Canon® Monochrome Universal Chip Chart

NOTE: Chip appearance subject to change. Pictures and images may not be reflective of current offering.




| Static Control Chip | Printer Model | OEM SKU | Yield | Picture |
|--|--|---|-------|---|
| U29CHIP SSST™ 1017 Chip Marking (U29) | Canon® D530, D550, FAXPHONE L190, MF4410, MF4412, MF4420, MF4430, MF4450, MF4550, MF4570, MF4580, MF4770, MF4870, MF4880, MF4890 | CRG-128 CRG-328 CRG-728 | 2.1k |  |
| | HP® P1005, P1006 | CB435A (35A) | 1.5k | |
| | Canon® LBP-3010, LBP-3018, LBP-3050, LBP-3100, LBP-3108, LBP-3150 | CRG-312, CRG-712, CRG-912 | | |
| | HP® P1102, M1130 MFP, M1132 MFP, M1212 MFP, M1214 MFP, M1217 MFP, M1219 MFP | CE285A | 1.6k | |
| | Canon® MF-3010, LBP-6000, LBP-6030 | CRG-125, CRG-325, CRG-725 | | |
| | HP® P1505, M1120 MFP, M1522 MFP | CB436A (36A) | 2k | |
| | Canon® LBP-3250 | CRG-313, CRG-713 | | |
| | HP® M1536 MFP, P1566, P1606 | CE278A | 2.1k | |
| Canon® LBP-6200 | CRG-326, CRG-726 | | | |
| U30CHIP SSST™ 1017 Chip Marking (U30) | Canon® D530, D550, FAXPHONE L190, MF4410, MF4412, MF4420, MF4430, MF4450, MF4550, MF4570, MF4580, MF4770, MF4870, MF4880, MF4890 | CRG-128 (Intro) CRG-328 (Intro) CRG-728 (Intro) | 1k |  |
| | Canon® D1120 MFP, D1150 MFP, D1170 MFP, D1180 MFP, D1320, D1350, D1370, MF6680, MF6780 | CRG-120 (Intro) CRG-320 (Intro) CRG-720 (Intro) | 2.3k | |
| | HP® P1102, M1130 MFP, M1132 MFP, M1212 MFP, M1214 MFP, M1217 MFP, M1219 MFP | CE285A (Intro) | 0.7k | |
| | Canon® MF-3010, LBP-6000, LBP-6030 | CRG-125 (Intro) CRG-325 (Intro) CRG-725 (Intro) | | |
| | HP® M1536 MFP, P1566, P1606 | CE278A (Intro) | 1k | |
| | Canon® LBP-6200 | CRG-326 (Intro) CRG-726 (Intro) | 0.9k | |





HP® and Canon® Monochrome Universal Chip Chart

NOTE: Chip appearance subject to change. Pictures and images may not be reflective of current offering.

| Static Control Chip | Printer Model | OEM SKU | Yield | Picture |
|---|--|-----------------|-------|--|
| U35-2CHIP SSS™ 1014 Chip Marking (U35-2) | HP® M125/M127 MFP, M201, M202 MFP | CF283A | 1.5k |  |
| | HP® M225 MFP | CF283X | 2.2k | |
| | HP® 400 M401, 400 M425 MFP | CF280A (HP 80A) | 2.7k | |
| | HP® 600 M601, 600 M602, 600 M603, M4555 MFP | CE390A (HP 90A) | 10k | |
| U36-3CHIP SSS™ 1017 Chip Marking (U36-3) | HP® 400 M401, 400 M425 MFP | CF280X | 6.9k |  |
| | HP® 600 M602, 600 M603, M4555 MFP | CE390X | 24k | |
| | HP® 800 M806, 800 M830 MFP | CF325X | 34.5k | |
| Static Control Chip | Printer Model | OEM SKU | Yield | Picture |
| U5-2CHIP SSS™ 914 Chip Marking (U5-2) | HP® 4100 | C8061X | 10k |  |
| | HP® 9000, 9040 MFP, M9040 MFP, 9050 MFP, M9050 MFP | C8543X | 30k | |